

Search Notes**Application/Control No.**

10/771,083

Examiner

Toan M. Le

Applicant(s)/Patent under Reexamination

HOFMEISTER ET AL.

Art Unit

2863

SEARCHED

Class	Subclass	Date	Examiner
702	120	5/24/2005	TL
372	38.1	5/12/2005	TL
372	50	5/12/2005	TL
257	688	5/20/2005	TL
385	92	5/20/2005	TL
385	93	5/20/2005	TL
372	38.02	5/23/2005	TL
Above	Updated	12/22/2005	TL
Above	Updated	7/21/2006	TL
398	135	7/21/2006	TL
Above	Updated	3/3/2007	TL
372	26,29.021	3/3/2007	TL
398	182,186	3/3/2007	TL

INTERFERENCE SEARCHED

Class	Subclass	Date	Examiner

**SEARCH NOTES
(INCLUDING SEARCH STRATEGY)**

	DATE	EXMR
Electrostatic Discharge Damage, Photodiode, Laser	5/12/2005	TL
Laser Diode, Switch, Transceiver, Pins	5/12/2005	TL
Transceiver Module, Laser Diode	5/12/2005	TL
VCSEL, Laser Drive, Laser Diode, Transceiver	5/23/2005	TL
702/120; 372/38.1,38.02; 257/688; 398/135 (Laser Diode)	7/21/2006	TL
702/120; 372/26,29.021,38.1,38.02,50; 257/688; 385/92,93; 398/135,182,186 (VCSEL Operating reference Characteristics)	3/3/2007	TL
East- See Search History Printout	3/3/2007	TL